


\*\*\* Mr. Machinist Bolt Circle Coordinates \*\*\*



12 Holes/12.5000 Dia. Bolt Circle

X Center Line = -1.2500

Y Center Line = 0.0000

1st Hole is at: 45.2000 Degrees

C/Line Distance = 3.2352

Hole Wall Distance = 2.7352

Hole Diameter = 0.5000